






220 / 440 / 3 / 60



JUMPERS 220V ONLY

STARTING SERIAL NUMBER 480

GROB INC. GRAFTON, WIS.

Schematic Wiring Diagram
for 6V-36 Band Saw

NO. REQ'D	PATT. NO.	MATERIAL	HEAT TREATMENT	DRN SV	TR	CR	DRW. NO.
				DATE 8-9-01	SCALE	OK	HS-964-C